

About Our Airstream Repairs Pricing Guide

“Making Airstream Repairs Affordable”

Body Repairs: Use this pricing guide to provide a “rough estimate”. Your trailer may have differences such as trim packages or additional damage that could cause the price to be higher. We will need good photographs of the damage, including close ups, and overall shots that show the adjoining body segments **and** shots that show the entire trailer. We will also ask for your VIN number because we work closely with the Airstream factory to make sure we are sourcing the correct parts for your trailer.

At GT Services we are brutally honest with our cost estimates. Go to your local Airstream dealer, get an estimate if you can, then contact us and email photos. Most likely, you will be very surprised at the difference!

GT Services Inc pricing is normally 20% - 50% lower than your local Airstream dealer would charge. “What is the catch” you ask?

As America’s premier Airstream restorer, we often are called upon to disassemble and reassemble major sections of these iconic trailers as part of the restoration process. The simple truth is that a typical Airstream dealer does not do this type of extensive repairs, and most are uncomfortable quoting pricing and / or doing the work. They simply do not have our depth of knowledge and experience in dealing with these major repairs. Our quality of work is the best in the business because we have the expertise gained from doing hundreds of major restorations and repairs.

Our advantage is also lower overhead. We don’t have big fancy offices with secretaries and pesky sales people. When you check in for your repair appointment you will talk directly with our shop foreman, who will provide you with all the information that you need regarding your repairs.

Body segments are currently available from the Airstream factory for model years 1969 through 2024. These are ORIGINAL FACTORY PARTS, not reproductions. In some instances, on a case-by-case basis, our talented metalworking staff can fabricate certain body parts for 1968 and earlier trailers.

Typical Body Repair Pricing, Including Parts 1969-2024 Models

- One segment replacement: \$5200.00
- Two adjacent segments: \$7400.00
- Three adjacent segments: \$10900.00
- Newer model Airstream segment with corner window if the window is OK \$6200.00
- Lower side panel replacement – newer models Ask for quote
- Upper side panel replacement – newer models Ask for quote
- 1969 and up, front corner window and installation, \$1650.00

If available

Typical Appliance Replacement Pricing, Including Parts

- Air conditioner replacement, 13,500 BTU \$2600.00
- Air conditioner replacement, 15,000 BTU \$2900.00
- Hot water heater replacement, 6 gallon \$1715.00
- Hot water heater replacement, on demand \$1675.00
- New propane furnace, ducted replacement \$2400.00
- Powered reversible vent fan with rain sensors \$975.00
- Airstream basic window rehabilitation most trailers \$225.00
- Airstream Vista View window service \$840.00
- Airstream entry step replacement \$600.00
- Airstream comprehensive shell inspection \$800-\$1200
- Airstream electric jack replacement \$450.00
- Basic Zamp 90 watt solar power system for Airstream \$2300.00

Rear End Separation

- Flat fee, almost any Airstream trailer \$6950.00

Dexter Torsion Axles, The Gold Standard for Airstream

- Typical dual axle installation, with new shock absorbers \$4600.00
- Older models with spring axles, case-by-case basis